

BCS3600^{ex}-IS Hand-held scanner

Accessories



It is absolutely necessary to use original accessories from BARTEC!

Accessories for use in hazardous areas

Accessories are approved for:

- ATEX: Zone 1/21 (EPS 18 ATEX 1 199 X + EPS 17 ATEX 1 177 X)
- IECEx: Zone 1/21 (IECEx EPS 18.0100X + IECEx EPS 17.0090X)
- UL: Zone 0/20 and Class I, II, III Division 1 (E3226123)



Battery

Description	– for BCS3678 ^{ex} -IS Hand-held scanner – Lithium-Ion battery 3.6 V/2800 mAh (10.08 Wh) May only be changed and charged outside hazardous areas!
Order no.	17-A1Z0-0012



Leather holster

Description	– for attachment to a belt or wall – Color: black
Order no.	17-A1Z0-0024



Connecting cable

Description	– Connection between supply module and BCS3608 ^{ex} -IS Hand-held scanner	
Order no.	1.9 m (plain)	17-A1Z0-0015
	4.5 m (plain)	17-A1Z0-0016
	2.7 m (spiral)	17-A1Z0-0017

Accessories for use outside hazardous areas



4-slot battery charging station

Description	<ul style="list-style-type: none"> – for BCS3678^{EX}-IS Hand-held scanner – input voltage: DC 12 V (50 W) – Charging indicator via LED
Scope of delivery	4-slot battery charging station
Also required	(Not included in the delivery) <ul style="list-style-type: none"> – Power supply with DC connecting cable (G7-A0Z0-0019) – AC power cable
Order no.	17-A1Z0-0013



Base station

Description	<ul style="list-style-type: none"> – for BCS3678^{EX}-IS Hand-held scanner – Input voltage: DC 12 V – Data synchronisation via Bluetooth, Supported interfaces (full functionality as specified by Zebra): USB + RS232 – Charging the battery inserted in the hand-held scanner – Charging function and charging indicator via LED – can be mounted on wall or table Operating mode: <ul style="list-style-type: none"> – Point-to-Point (1x scanner paired with 1x base station - default setting) – Multipoint-to-Point (7x scanners can be paired with 1x base station)
Scope of delivery	Base station
Also required	(Not included in the delivery) <ul style="list-style-type: none"> – Power supply with DC connecting cable (G7-A0Z0-0019) – AC power cable – Connecting cable RS232 or USB (17-A1Z0-....)* * Connecting cable absolutely necessary between power supply and base station. Power supply cannot be connected directly to the base station.
Order no.	17-A1Z0-0014



Programming cable USB

Description	<ul style="list-style-type: none"> – identical with Connecting cable USB – Programming BCS3608^{ex}-IS via PC – Programming BCS3678^{ex}-IS via PC and base station – 1.9 m (plain)
Scope of delivery	Programming cable USB
Also required	(Not included in the delivery) <ul style="list-style-type: none"> – Power supply with DC connecting cable (G7-A0Z0-0019) – AC power cable – Base station (when using the BCS3678^{ex}-IS)
Order no.	17-A1Z0-0020



Connecting cable RS232

Description	<ul style="list-style-type: none"> – for BCS3678^{ex}-IS Hand-held scanner – Connection between PC and base station – Cable with terminal for 12 V power supply
Scope of delivery	Connecting cable RS232
Also required	(Not included in the delivery) <ul style="list-style-type: none"> – Power supply with DC connecting cable (G7-A0Z0-0019) – AC power cable
Order no.	1.9 m (plain) 17-A1Z0-0026 4.5 m (plain) 17-A1Z0-0027



Connecting cable USB

Description	<ul style="list-style-type: none"> – identical with programming cable USB – for BCS3678^{ex}-IS Hand-held scanner – Connection between PC and Base station – Cable with terminal for 12 V power supply – 1.9 m (plain)
Scope of delivery	Connecting cable USB
Also required	(Not included in the delivery) <ul style="list-style-type: none"> – Power supply with DC connecting cable (G7-A0Z0-0019) – AC power cable
Order no.	17-A1Z0-0020




Power supply with DC connecting cable

Description	<ul style="list-style-type: none"> – for 4-slot battery charging station and base station – Input voltage: AC 100 to 240 V – Output voltage: DC 12 V/4.16 A/50 W
Order no.	G7-A0Z0-0019



AC power cable

Description	– 3-wire – country-specific	
Order no.	Version: US + Canada	G7-A0Z0-0024
	Version: EU + APAC	G7-A0Z0-0026
	Version: Taiwan	G7-A0Z0-0027
Please purchase the required country specific cables (with plug IEC-60320-C13) in the respective country!		



Special tool for lock nut

Description	– for BCS3678 ^{ex} Hand-held scanner – open and lock the safety lock nut on the battery compartment – 5 pieces	
Order no.	G7-A0Z0-0031	



Call: 866.724.6257

EMAIL: SALES@GLACIERCOMPUTER.COM

VISIT: GLACIERCOMPUTER.COM